

Monday, March 27, 2017 4:18:13 PM

158599

N900040100

Setup Start *NS1*

Stop *NS2*

Start Date: 3/30/2017 **Start Qty:** 1.00 ***1***

Cust Item ID:

Required Date: 3/31/2017 **Req'd Qty:** 1.00 ***1***

Customer:

Reference: SCHEDULED/C

Approvals: Process Plan: Date: MAR 27 2017 Tooling: Date:

Run Start *NR1*

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop *NR2*

[illegible]

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER : _____							

Work Order ID 158599

Monday, March 27, 2017 4:18:13 PM

158599

Page 2

Item ID: D350-567-115B

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Interior Floor Window, Blank

Start Date: 3/30/2017 Start Qty: 1.00

1

Cust Item ID:

Required Date: 3/31/2017 Req'd Qty: 1.00

1

Customer:

Reference: SCHEDULED/C

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start

NR1

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120	QC4- 100% Inspect kits for completeness	0.00							
120						DAS 27 9-89			
QC	Memo	0.03							
Quality Control									
									APR 06 2017
130		0.00							
130	Packaging								
Packaging	Memo	0.00				DAS 28 9-89	DAS 27 9-89		
Packaging	Identify and pack for shipping as per PPP D350-567-115b								
	Location: _____								
	PPP Rev: _____								
									APR 06 2017
140	QC21- Final Inspection - Work Order Release	0.00							
140						DAS 21 9-89			
QC	Memo	0.10							
Quality Control									
									APR 06 2017

DAS
21
9-89

APR 06 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																																																										
Description Work Order Deviation				Disposition				Completed By																																																									
								Lead hand / Supervisor Approval Verification																																																									
								QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐																																																																

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐				FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐					
OTHER : _____									

Picklist Print

Page 2

Monday, March 27, 2017 4:18:27 PM

Work Order ID: 158599

158599

Parent Item: D350-567-115B

D350-567-115R

Parent Item Name: Interior Floor Window, Blank

Start Date: 3/30/2017

Required Date: 3/31/2017

Start Qty: 1.00

Required Qty: 1.00

MS21062L3
Purchased No
MS21062L3
Nut Plate

110 Each 48.0000 4 4

**

Location

Loc Qty

Loc Code

ST300

48

m135043

8

m136787

10

m136983

30

MAR 30 2017

D3293-1B
Manufactured No
D3293-1B
Doubler, Blank

110 Each 0.0000 1 1

**

D3294-1B
Manufactured No
D3294-1B
Bracket, Blank

110 Each 0.0000 1 1

**

D3295-041B
Manufactured No
D3295-041B
Floor Window, Blank

110 Each 0.0000 1 1

**

D3296-041B
Manufactured No
D3296-041B
Door Assembly, Blank

110 Each 0.0000 1 1

**

D2463
Manufactured No
D2463
1/2" Seal (\$ per foot)

110 f 189.9505 4.416 4.416

**

Location

Loc Qty

Loc Code

ST409

189.9504587

140013

3.9081E-05

148875

189.95042

MAR 30 2017

(D2463-0530) CUT (1) AT 53.00" PER KIT

Monday, March 27, 2017 4:18:27 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : _____							

Picklist Print

Page 3

Monday, March 27, 2017 4:18:27 PM

Work Order ID: 158599

158599

Parent Item: D350-567-115B

D350-567-115B

Parent Item Name: Interior Floor Window, Blank

Start Date: 3/30/2017

Required Date: 3/31/2017

Start Qty: 1.00

Required Qty: 1.00

AN526C632R12 Purchased No

110 Each 149.0000 9 9

AN526C632R12

Screw

**

MAR 30 2017

DAS 28
6 9-89

DAS 27
9-89

Location

Loc Qty

Loc Code

ST327

149

m135766

49

m136741

100

9

NAS1149DN632J Purchased No

110 Each 318.0000 6 6

NAS1149DN632J

Washer

**

MAR 30 2017

DAS 28
6 9-89

DAS 27
9-89

Location

Loc Qty

Loc Code

ST265

318

m134370

318

6

MS21042I 06 Purchased No

110 Each 134.0000 9 9

MS21042I 06

Nut

**

MAR 30 2017

DAS 28
6 9-89

DAS 27
9-89

Location

Loc Qty

Loc Code

OVER007

50

m137061

50

ST303

84

m136741

84

9

MS20470AD4-5 Purchased No

110 Each 2,397.000 2 2

MS20470AD4-5

RIVET, UNIVERSAL HEAD

**

MAR 30 2017

DAS 28
6 9-89

DAS 27
9-89

Location

Loc Qty

Loc Code

GA

1741

m136851

1741

ST310

656

m134654

656

2

Monday, March 27, 2017 4:18:27 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐		Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐					
		OTHER : _____							

Picklist Print

Monday, March 27, 2017 4:18:27 PM

Work Order ID: 158599

158599

Parent Item: D350-567-115B

D350-567-115B

Parent Item Name: Interior Floor Window, Blank

Start Date: 3/30/2017

Required Date: 3/31/2017

Start Qty: 1.00

Required Qty: 1.00

MS20470AD4-6

Purchased

No

110

Each

2,024.000

115

115

MS20470AD4-6

Rivet, Universal Head

MAR 30 2017

DAS 6 9-89
DAS 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

CCK004

1566

m136787

1566

GA

352

m133077

352

ST310

106

m134852

106

103

12

MS20470AD4-7

Purchased

No

110

Each

1,830.000

15

15

MS20470AD4-7

Rivet, Universal Head

MAR 30 2017

DAS 6 9-89
DAS 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

CCK004

1821.604

m134376

1396

m134630

425.604

LG001

1.396

m134630

1.396

ST310

7

m132536

7

13

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D350-567 REV. E
AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D350-567 REV. 2

REF. TCCA STC: SH92-18

REF. FAA STC: SH989NE AND SH990NE

REF. EASA STC: EASA.IM.R.S.01560 AND EASA.IM.R.S.01561

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 15859
MAR 27 2017

PURPOSE:

To provide a new location for the cabin fire extinguisher for aircraft equipped with P/N 19810-02-00 (SICMA-198 Seat). For further information on SICMA-198 Seats refer to Airbus CMM 25-12-31.

CHANGE:

For aircraft equipped with P/N 19810-02-00 (SICMA-198 Seat) add section 3.2.3, amend section 5.0 Parts List (ICA Section 25.7) and amend section 4.0 Weight and Balance (ICA Section 25.5) of Vertical Reference Window Installation Instructions D350-567 Rev. E (ICA D350-567 Rev. 2) as follows:

- (ADD) 3.2.3 This installation will require access to the under floor structure in the area aft of the pilot's collective stick. To access the under floor structure remove the applicable belly panel in accordance with the applicable Aircraft Maintenance Manual.

Remove and retain the cabin fire extinguisher P/N 1708337 B4 and Fire Extinguisher Support P/N 350A77 0131 40 from existing location. Per Figure 1, select the desired location for the fire extinguisher at either the "Primary" location or "Alternate" location.

Locate the D5420-1 Doubler Plate at the selected location per Figure 1 and transfer mark the holes from the D5420-1 Doubler Plate to the aircraft floor. Drill the nutplate hole pattern shown in Detail A. Touch up the drilled floor surface finish with chemical film (Alodine 1200/1201) per MIL-C-5541 and one coat of MIL-P-85582 or MIL-P-23377 primer.

Locate the D5420-1 Doubler Plate under the floor and install using qty (4) MS21062L3 nutplates and qty (8) MS20426AD3-5 Rivets (rivets fasten through floor and doubler). Locate the Fire Extinguisher Support P/N 350A77 0131 40 over the drilled holes and fasten it to the qty (4) MS21062L3 nutplates using qty (4) AN3-3A Bolts. Torque bolts 20-25 in-lbs (2.3-2.8 N-m). Reinstall the P/N 1708337 Fire Extinguisher per the Aircraft Maintenance Manual.

Reinstall the belly panel per the applicable Aircraft Maintenance Manual.

CHANGE:

Amend Section 25.6 Equipment relocation of ICA D350-567 Rev. 2 as follows:

25.6 EQUIPMENT RELOCATION

- (IS) As part of the D350-567 kit installation, the aircraft data plate may have been relocated beneath the RH pilot's seat and the fire extinguisher may have been relocated to the LH side of the pilot's seat per Eurocopter Service Bulletin 25.00.59. See also Dart Drawing D350-567.

Depending on the Aircraft's seating configuration the fire extinguisher may have to be relocated to the LH side of the pilot's seat per Eurocopter Service Bulletin 25.00.59, or relocated to the cabin floor per Dart DSI 9745. See also Dart Drawing D350-567.

- (WAS) As part of the D350-567 kit installation, the aircraft data plate may have been relocated beneath the RH pilot's seat and the fire extinguisher may have been relocated to the LH side of the pilot's seat per Eurocopter Service Bulletin 25.00.59. See also Dart Drawing D350-567.

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-O-01	
APPROVED	
BY:	
D. SHEPHERD (DE # 02)	
DATE:	16.04.06
CERT. NO.:	SH92-18
ISSUE NO.:	6

A	NEW ISSUE (SEE PAR 16-510)	AJS	16.04.06
REV.	DESCRIPTION	BY	DATE
DESIGN	AJS	DART AEROSPACE LTD	
DRAWN	AJS	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9745	SHEET 1 OF 3
APPROVED		TITLE	SCALE
DE APPR.		ALTERNATE FIRE EX LOCATION	NTS
DATE	16.04.06	COPYRIGHT © 2016 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			

EDIT 5.0/25.7 PARTS LIST:

For customers with kits D350-567-013/-015/-017/-023/-025/-027/-117 @ CHG002 and earlier,
 Customers with kits D350-567-111 @ CHG006 and earlier,
 Customers with kits D350-567-115 @ CHG004 and earlier,
 Customers with kits D350-567-031/-031B/-111B/-115B @ CHG001 and earlier,
 Procure kit DSI 9745-011

Item	Qty -011	Part Number	Description
	X	DSI 9745-011	FIRE EXTINGUISHER RELOCATION KIT
1	1	D5420-1	DOUBLER PLATE
2	4	AN3-4A	HEX HEAD BOLT
3	8	MS20426AD3-5	CSK RIVET
4	4	MS21062L3	NUTPLATE

For customers with kits D350-567-013/-015/-017/-023/-025/117 @ CHG003 and later,
 Customers with kits D350-567-111 @ CHG007 and later,
 Customers with kits D350-567-115 @ CHG005 and later,
 Customers with kits D350-567-031/-031B/-111B/-115B @ CHG002 and later,
 Refer to Installation Instructions D350-567 and ICA-D350-567 and update the parts list as follows:


EDIT 5.0 ADD:

Qty -013	Qty -023	Qty -113	Qty -115	Qty -031	Part Number	Description
X					D350-567-013	REPLACEMENT WINDOW KIT (SMALL)
	X				D350-567-023	REPLACEMENT WINDOW KIT (LARGE)
		X			D350-567-113	REPLACEMENT WINDOW KIT (EXTRA LARGE)
			X		D350-567-115	INTERIOR FLOOR WINDOW KIT
				X	D350-567-031	INTERIOR FLOOR WINDOW KIT (SLIDING DOOR COMPATABLE)
			1	1	D5420-1	DOUBLER PLATE
			4	4	AN3-4A	HEX HEAD BOLT
			8	8	MS20426AD3-5	CSK RIVET
			4	4	MS21062L3	NUTPLATE

EDIT 4.0/25.5 WEIGHT AND BALANCE:

*Note: Does not include fire extinguisher weight

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
DSI 9745-011 (Primary Location)	0.1 lb	+1.6 in	+16 in lb	72.2 in	7.2 in lb
Fire Extinguisher Relocation Kit	0.05 kg	+0.04 m	+0.02 m kg	1.83 m	0.1 m kg
DSI 9745-011 (Alternate location)	0.1 lb	-4.4 in	-44 in lb	65.4 in	6.5 in lb
Fire Extinguisher Relocation Kit	0.05 kg	-0.11 m	-0.01 m kg	1.66 m	0.1 m kg

**DETAIL A**

(NUT PLATE HOLE PATTERN)

CANADA
 DEPARTMENT OF TRANSPORT
 AIRCRAFT CERTIFICATION
 BRANCH
 DAO # 01-0-01

APPROVED

BY: *[Signature]*
 D. SHEPHERD (DE # 02)

DATE: 16.04.06
 CERT. NO.: SH92-18
 ISSUE NO.: 6

DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9745	SHEET 2 OF 3
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	ALTERNATE FIRE EX LOCATION	NTS
DATE	16.04.06	COPYRIGHT © 2016 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	




FIGURE 1

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED
BY: *[Signature]*
D. SHEPHERD (DE # 02)
DATE: 16.04.06
CERT. NO.: SH92-18
ISSUE NO.: 6

DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9745	SHEET 3 OF 3
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	ALTERNATE FIRE EX LOCATION	NTS
DATE	16.04.06	COPYRIGHT © 2016 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

5.0 PARTS LIST

Qty -015	Qty -017	Qty -025	Qty -027	Qty -111	Qty -117	Part Number	Description
X						D350-567-015	FLOOR WINDOW INSTALLATION (SMALL)
	X					D350-567-017	FLOOR WINDOW INSTALLATION (SMALL)
		X				D350-567-025	FLOOR WINDOW INSTALLATION (LARGE)
			X			D350-567-027	FLOOR WINDOW INSTALLATION (LARGE)
				X		D350-567-111	FLOOR WINDOW INSTALLATION (EXTRA LARGE)
					X	D350-567-117	FLOOR WINDOW INSTALLATION (EXTRA LARGE)
1	1					D350-567-013	REPLACEMENT WINDOW KIT (SMALL)
		1	1			D350-567-023	REPLACEMENT WINDOW KIT (LARGE)
				1	1	D350-567-113	REPLACEMENT WINDOW KIT (EXTRA LARGE)
	1		1	1		D350-567-115	INTERIOR FLOOR WINDOW KIT
1		1			1	D350-567-031	INTERIOR FLOOR WINDOW KIT (SLIDING DOOR COMPATABLE)

Qty -013	Qty -023	Qty -113	Qty -115	Qty -031	Part Number	Description
X					D350-567-013	REPLACEMENT WINDOW KIT (SMALL)
	X				D350-567-023	REPLACEMENT WINDOW KIT (LARGE)
		X			D350-567-113	REPLACEMENT WINDOW KIT (EXTRA LARGE)
			X		D350-567-115	INTERIOR FLOOR WINDOW KIT
				X	D350-567-031	INTERIOR FLOOR WINDOW KIT (SLIDING DOOR COMPATABLE)
1					D2125	REPLACEMENT WINDOW, SMALL
	1				D2942	REPLACEMENT WINDOW, LARGE
		1			D3290-041	REPLACEMENT WINDOW ASSEMBLY, EXTRA LARGE
1					D2126-0600	SEAL
	1				D2463-0750	NEOPRENE SEAL
		1			D2463-0860	NEOPRENE SEAL
	9	12			2600-6	1/4 TURN FASTENER
	9	12			2600-LW	WASHER
	9	12			212-12	RECEPTACLE
	22	21			AN526C832R9	SCREW (OR AN526C832-9, OR MS51957-126)
	44	42			AN960JD8	WASHER
	22	21			MS21042L08	NUT (OR MS21042-08)
	18	24			MS20426AD3-5	RIVET
2 SQ. YD	2 SQ. YD	2 SQ. YD			N/A	9.7oz 7781 'S' GLASS UNIVERSAL WEAVE
				1	D2463-0450	NEOPRENE SEAL
				1	D3210-1	DOUBLER
				1	D3211-1	BRACKET
				1	D3212-1	FLOOR WINDOW
				1	D3213-041	DOOR ASSEMBLY
			1		D3293-1	DOUBLER
			1		D3294-1	BRACKET
			1		D3295-041	FLOOR WINDOW
			1		D3296-041	DOOR ASSEMBLY
			1		D2463-0530	NEOPRENE SEAL
		9	8		AN526C632R12	SCREW (OR AN526C632-12, OR MS51957-32)
		9	8		AN960JD6	WASHER
		9	8		MS21042L06	NUT (OR MS21042-06)
		2	40		MS20470AD4-5	RIVET
		115	90		MS20470AD4-6	RIVET
		15	20		MS20470AD4-7	RIVET

REFERENCE ONLY

EDIT 5.0/25.7 PARTS LIST:

For customers with kits D350-567-013/-015/-017/-023/-025/-027/-117 @ CHG002 and earlier,
 Customers with kits D350-567-111 @ CHG006 and earlier,
 Customers with kits D350-567-115 @ CHG004 and earlier,
 Customers with kits D350-567-031/-031B/-111B/-115B @ CHG001 and earlier,
 Procure kit DSI 9745-011

Item	Qty -011	Part Number	Description
	X	DSI 9745-011	FIRE EXTINGUISHER RELOCATION KIT
1	1	D5420-1	DOUBLER PLATE
2	4	AN3-4A	HEX HEAD BOLT
3	8	MS20426AD3-5	CSK RIVET
4	4	MS21062L3	NUTPLATE

For customers with kits D350-567-013/-015/-017/-023/-025/117 @ CHG003 and later,
 Customers with kits D350-567-111 @ CHG007 and later,
 Customers with kits D350-567-115 @ CHG005 and later,
 Customers with kits D350-567-031/-031B/-111B/-115B @ CHG002 and later,
 Refer to Installation Instructions D350-567 and ICA-D350-567 and update the parts list as follows:


EDIT 5.0 ADD:

Qty -013	Qty -023	Qty -113	Qty -115	Qty -031	Part Number	Description
X					D350-567-013	REPLACEMENT WINDOW KIT (SMALL)
	X				D350-567-023	REPLACEMENT WINDOW KIT (LARGE)
		X			D350-567-113	REPLACEMENT WINDOW KIT (EXTRA LARGE)
			X		D350-567-115	INTERIOR FLOOR WINDOW KIT
				X	D350-567-031	INTERIOR FLOOR WINDOW KIT (SLIDING DOOR COMPATABLE)
			1	1	D5420-1	DOUBLER PLATE
			4	4	AN3-4A	HEX HEAD BOLT
			8	8	MS20426AD3-5	CSK RIVET
			4	4	MS21062L3	NUTPLATE

EDIT 4.0/25.5 WEIGHT AND BALANCE:

*Note: Does not include fire extinguisher weight

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
DSI 9745-011 (Primary Location)	0.1 lb	+1.6 in	+16 in lb	72.2 in	7.2 in lb
Fire Extinguisher Relocation Kit	0.05 kg	+0.04 m	+0.02 m kg	1.83 m	0.1 m kg
DSI 9745-011 (Alternate location)	0.1 lb	-4.4 in	-44 in lb	65.4 in	6.5 in lb
Fire Extinguisher Relocation Kit	0.05 kg	-0.11 m	-0.01 m kg	1.66 m	0.1 m kg



DETAIL A

(NUT PLATE HOLE PATTERN)

CANADA
 DEPARTMENT OF TRANSPORT
 AIRCRAFT CERTIFICATION
 BRANCH
 DAO # 01-O-01

APPROVED
 BY: *[Signature]*
 D. SHEPHERD (DE # 02)

DATE: 16.04.06
 CERT. NO.: SH92-18
 ISSUE NO.: 6

DESIGN	AJS	DART AEROSPACE LTD	
DRAWN	AJS	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9745	SHEET 2 OF 3
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	ALTERNATE FIRE EX LOCATION	NTS
DATE	16.04.06	COPYRIGHT © 2016 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	